



13.10.2014

Üretimini yapmakta olduğumuz Sabit Kapaklı Tapalı , Laksız Dkp sac variller üzerinde ,AYTAŞ TARIM ÜRÜNLERİ SANAYİ VE TİCARET A.Ş. firmasının ürettiği ETHANOL(ETİL ALKOL) korozyon testi denemesi 3 ay süreyle yapılmış ve varillerde herhangi bir korozyon yada pas gözlemlenmemiştir. Varilin paslanması sebep olabilecek nem, su teması , açık bırakılan kapak vb. konular sorumluluğumuz dışındadır.



SEYDİOĞLU AMBALAJ SAN. ve TİC. LTD. ŞTİ.
A.O.S.B. 10040 Sokak No:22 Çiğli - İZMİR
Çağrı V.D. 766 066 1676

The drums which we are manufacturing, the inquiry tests of the aytas about corrosion and rust tests, we did tests and waited ethanol in drums for 3 months and the result is drums were passed the tests for 3 months. We didnt see any corrosion or dust in 3 months. And ethanol stil waiting in drums. Test drum was DKP steel and without laque. Also the condition of the stroge at the drums are important, like as huminity, water, rain, unlocked tap etc. , if any rust happens becuase of the wrong storage conditions we dont have any responsibility.



SEYDİOĞLU AMBALAJ SAN. ve TİC. LTD. ŞTİ.
A.O.S.B. 10040 Sokak No:22 Çiğli - İZMİR
Çağrı V.D. 766 066 1676